

# DANLERS

Your ref:

Our ref:

Date:

---

DANLERS Limited  
Vincients Road  
CHIPPENHAM  
Wiltshire SN14 6NQ  
United Kingdom

---

Tel: +44 (0)1249 443377  
Fax: +44 (0)1249 443388  
E-mail: [sales@danlers.co.uk](mailto:sales@danlers.co.uk)  
[www.danlers.co.uk](http://www.danlers.co.uk)

---


CAPLOAD - INS194.indd/2

Product: 2-wire, plated, time lag switch.

Problem: Intermittent function.

Cause: Resistive load less than 40W (approx 100W inductive).

Solution: Wire a CAPLOAD power factor correction capacitor in parallel with load.



With Compliments

# DANLERS

Your ref:

Our ref:

Date:

---

DANLERS Limited  
Vincients Road  
CHIPPENHAM  
Wiltshire SN14 6NQ  
United Kingdom

---

Tel: +44 (0)1249 443377  
Fax: +44 (0)1249 443388  
E-mail: [sales@danlers.co.uk](mailto:sales@danlers.co.uk)  
[www.danlers.co.uk](http://www.danlers.co.uk)

---


CAPLOAD - INS194.indd/1

Product: 2-wire PIR switch.

Problem: Device locked on or off.

Cause: Resistive load less than 40W (approx 100W inductive).

Solution: Wire a CAPLOAD power factor correction capacitor in parallel with load.  
Rechargeable battery may need to be removed, recharged and replaced.



With Compliments